



DEFENSE LOGISTICS AGENCY
LAND AND MARITIME
POST OFFICE BOX 3990
COLUMBUS, OH 43218-3990

April 11, 2018

Mr. Allen Wares
Quality Manager
Micross Components Orlando (MCO)
7725 N. Orange Blossom Trail
Orlando, FL 32810

Dear Mr. Wares:

Re: Q and V Level Assembly and Test Certification; MIL-PRF-38535; FSC 5962; VQC-18-032474; Control Number 062154

Micross Components Orlando (MCO) has demonstrated to the DLA Land and Maritime that it complies with MIL-PRF-38535, the performance specification used by the Department of Defense for monolithic integrated circuits.

Micross Components Orlando (MCO) is granted Q and V Level Assembly and Test Certification for the process flows and materials used to assemble and test QML products for the quality assurance levels listed in the enclosure. This assembly and test certification listing includes subcontractors approved by MCO and as documented in their Quality Management Plan.

Testing must be performed using the facilities and methods listed in the Laboratory Suitability letter DLA Land and Maritime- VQC-18-032473, or at facilities approved by MCO's Technical Review Board (TRB) using its MIL-PRF-38535 Quality Management Program Plan.

This certification is subject to the conditions in DoD 4120.24-M, Defense Standardization Program and SD-6.

All of the facilities mentioned on the enclosure are subject to an audit by the DLA Land and Maritime Qualifying Activity at any time.

MCO shall notify the DLA Land and Maritime Qualifying Activity immediately after learning of a potential issuance of a GIDEP alert, problem advisory or major quality/reliability problem on their assembly and test processes. Failure to provide prior notification may be grounds for removal of their MIL-PRF-38535, Q and V Assembly and Test certification.

In addition, it is requested that the following activities be reported promptly to DLA Land

and Maritime:

- Changes to certified facilities, process flows, or approved testing subcontractors.
- Problem evaluation and a corrective action when:
 - A Technology Conformance Inspection (TCI) failure has been validated
 - The reliability of shipped parts is questionable.
- Test optimization, including:
 - Implementation - paragraph J.3.12, Appendix J, MIL-PRF-38535
 - Changing, suspending or canceling a prior test optimization
- Additions or deletions of parts in the QML-38535
- Change of company QML contact or other key QML personnel
- Changes in test methods and conditions

This Assembly and Test certification is valid until terminated by written notice from the DLA Land and Maritime Qualifying Activity. If warranted, it may be withdrawn by this center at any time.

If you have any questions please contact Mr. Paul Granchi, at (614) 692-9975.

Sincerely,

MICHAEL S. ADAMS
Chief
Sourcing and Qualification Division

cc:
DLA Land and Maritime-VQC (Scott Thomas)

Visit us on the web at: http://www.landandmaritime.dla.mil/offices/sourcing_and_qualification/

Package Assembly Capabilities:

<u>OPERATION</u>	<u>FACILITY</u>	<u>LOCATION</u>	<u>CAPABILITY</u>
Assembly	Micross Components Orlando (MCO)	7725 N. Orange Blossom Trail Orlando, FL 32810	
Die Attach Material	Micross Components Orlando (MCO)	7725 N. Orange Blossom Trail Orlando, FL 32810	Eutectic 80/20 AuSn, JM7000, 98/2 AuSi
Wire Type and Wire Size	Micross Components Orlando (MCO)	7725 N. Orange Blossom Trail Orlando, FL 32810	Al 1.0, 1.25, 4.0, 5.0
Lead Finish	Micross Components Orlando (MCO)	7725 N. Orange Blossom Trail Orlando, FL 32810	Gold Tin Lead
Sealing	Micross Components Orlando (MCO)	7725 N. Orange Blossom Trail Orlando, FL 32810	Solder seal, Parallel Seam seal, Projection Welding
Screening / Environmental Testing	Micross Components Orlando (MCO)	7725 N. Orange Blossom Trail Orlando, FL 32810	Screening as baselined by lab suitability information letter VQC-18-032473
Subcontractors	MMT Microchip Technology	17/2 Moo 18, Suwinthawong Road Tambol Saladang Amphur Bangnumpriew Chachoengsao	MIL-PRF-38535 Q and V assembly in accordance with Micross device specification flow MCO-Q-102.